

Picture C1: Radial gratings (Siemens-stars) *N-W, W-N, N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 0.6
Ergonomics − Visual Displays − Field Assessment Methods

input: *w* setgray*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 1.3
Ergonomics − Visual Displays − Field Assessment Methods

input: *w* setgray*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*



Picture C1: Radial gratings (Siemens-stars) *N-W, W-N, N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 5.0
Ergonomics − Visual Displays − Field Assessment Methods

input: *w* setgray*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W, W-N, N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 10.1
Ergonomics − Visual Displays − Field Assessment Methods

input: *w* setgray*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 20.2
Ergonomics − Visual Displays − Field Assessment Methods

input: *w* setgray*
output: *no change compared to input*



Picture C1: Radial gratings (Siemens-stars) *N-W*, *W-N*, *N-Z* and *W-Z*; PS operator: *w* setgray*



Picture C2: 5 visual equidistant *L**-grey steps + *N0* + *W1*; PS operator: *w* setgray*



Picture C3: 16 visual equidistant *L**-grey steps; PS operator: *w* setgray*



Picture C4: Landolt-rings *W-N*; PS operator: *w* setgray*



Picture C5: Line raster under 45° (or 135°); PS operator: *w* setgray*



Picture C6: Line raster under 90° (or 0°); PS operator: *w* setgray*

ISO 9241-test chart for contrast range *Yw:Yn* = 88.6 : 40.3
Ergonomics − Visual Displays − Field Assessment Methods

input: *w* setgray*
output: *no change compared to input*