www.ps.bam.de/LE04/10S/S04E02NP.PS/.PDF; start output
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)

See for similar files: http://www.ps.bam.de/LE04/LE04.HTM
Information and Order: http://www.ps.bam.de Version 2.0, io=0&1,0&1

BAM registration: 20030101-LE04/10S/S04E02NP.PS/.PDF BAM material: code=rha4ta
application for measurement of monitor (Yr=2.5) and printer output



used coordinate	surround	center
	c000*	o11*
C	1my0*	0lv*
	0m00*	1l1*
M	c1y0*	o0v*
	00y0*	11v*
Y	cm10*	ol0*
	0my0*	1lv*
O	c110*	o00*
	c0y0*	o1v*
L	1m10*	0l0*
	cm00*	ol1*
V	11y0*	00v*
	cmy0*	olv*
N/W	000k*	w*

16 equidistant CIELAB steps: *C−W, C−N, M−W, M−N, Y−W, Y−N, O−W, O−N, L−W, L−N, V−W, V−N, N−W, W−N* and 14 CIE-test colours (left)

Test chart LE04: 16 CIELAB steps of ISO/IEC 15775
Chromatic−White, Chromatic−Black, Black−White

input(ORS18): *cmyn*/olv* set(cmyk/rgb)color*
output(ORS18): *no change compared to input*