www.ps.bam.de/LE32/10Q/Q32E06NP.PS/.PDF; start output
N: No Output Linearization (OL) data in File (F), Startup (S) or Device (D)



used coordinate squares

LAB*TLS00
C
LAB*TLS00
LAB*TLS00
M
LAB*TLS00
LAB*TLS00
Y
LAB*TLS00
LAB*TLS00
O
LAB*TLS00
LAB*TLS00
L
LAB*TLS00
LAB*TLS00
V
LAB*TLS00
LAB*TLS00
N/W
LAB*TLS00

16 equidistant CIELAB steps: *C−W, C−N, M−W, M−N, Y−W, Y−N, O−W, O−N, L−W, L−N, V−W, V−N, N−W, W−N* and 14 CIE-test colours (left)

Test chart LE32: 16 CIELAB steps of ISO/IEC 15775
Chromatic−White, Chromatic−Black, Black−White

input(TLS00): *LAB* setcolor*
output(TLS00): *no change compared to input*

See for similar files: http://www.ps.bam.de/LE32/LE32.HTM
Information and Order: http://www.ps.bam.de Version 2.0, io=5,5

BAM registration: 20030101-LE32/10Q/Q32E06NP.PS/.PDF BAM material: code=rha4ta
application for measurement of monitor (Yr=2.5) and printer output



Picture D4w: 16 equidistant steps ***W-C, W-M, W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture B5w: Script and Landolt-rings ***N, C, M*** and ***Y***; PS operator *LAB* setcolor*



Picture B6w: Landolt-rings ***W-C*** and ***W-M***; PS operator *LAB* setcolor*



Picture B7w: Landolt-rings ***W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture D4w: 16 equidistant steps ***W-O, W-L, W-V*** and ***W-N***; PS operator *LAB* setcolor*



Picture D5w: Script and Landolt-rings ***N, O, L*** and ***V***; PS operator *LAB* setcolor*



Picture D6w: Landolt-rings ***W-O*** and ***W-L***; PS operator *LAB* setcolor*



Picture D7w: Landolt-rings ***W-V*** and ***W-N***; PS operator *LAB* setcolor*

Test chart LE32: 16 CIELAB steps of ISO/IEC 15775
Chromatic−White, Chromatic−Black, Black−White

input(TLS00): *LAB* setcolor*
output(TLS00): *no change compared to input*



Picture B4n: 16 equidistant steps ***W-C, W-M, W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture D5n: Script and Landolt-rings ***W, C, M*** and ***Y***; PS operator *LAB* setcolor*



Picture B6n: Landolt-rings ***N-C*** and ***N-M***; PS operator *LAB* setcolor*



Picture B7n: Landolt-rings ***W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture D4n: 16 equidistant steps ***W-O, W-L, W-V*** and ***W-N***; PS operator *LAB* setcolor*



Picture D5n: Script and Landolt-rings ***W, O, L*** and ***V***; PS operator *LAB* setcolor*



Picture D6n: Landolt-rings ***N-O*** and ***N-L***; PS operator *LAB* setcolor*



Picture D7n: Landolt-rings ***N-V*** and ***N-N***; PS operator *LAB* setcolor*

Test chart LE32: 16 CIELAB steps of ISO/IEC 15775
Chromatic−White, Chromatic−Black, Black−White

input(TLS00): *LAB* setcolor*
output(TLS00): *no change compared to input*

See for similar files: http://www.ps.bam.de/LE32/LE32.HTM
Information and Order: http://www.ps.bam.de Version 2.0, io=5,5



Picture B4n: 16 equidistant steps ***W-C, W-M, W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture D5n: Script and Landolt-rings ***W, C, M*** and ***Y***; PS operator *LAB* setcolor*



Picture B6n: Landolt-rings ***N-C*** and ***N-M***; PS operator *LAB* setcolor*



Picture B7n: Landolt-rings ***W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture D4w: 16 equidistant steps ***W-C, W-M, W-Y*** and ***W-N***; PS operator *LAB* setcolor*



Picture B5w: Script and Landolt-rings ***N, C, M*** and ***Y***; PS operator *LAB* setcolor*



Picture B6w: Landolt-rings ***W-C*** and ***W-M***; PS operator *LAB* setcolor*



Picture B7w: Landolt-rings ***W-Y*** and ***W-N***; PS operator *LAB* setcolor*

Test chart LE32: 16 CIELAB steps of ISO/IEC 15775
Chromatic−White, Chromatic−Black, Black−White

input(TLS00): *LAB* setcolor*
output(TLS00): *no change compared to input*



Picture D4n: 16 equidistant steps ***W-O, W-L, W-V*** and ***W-N***; PS operator *LAB* setcolor*



Picture D5n: Script and Landolt-rings ***W, O, L*** and ***V***; PS operator *LAB* setcolor*



Picture D6n: Landolt-rings ***N-O*** and ***N-L***; PS operator *LAB* setcolor*



Picture D7n: Landolt-rings ***N-V*** and ***N-N***; PS operator *LAB* setcolor*



Picture D4w: 16 equidistant steps ***W-O, W-L, W-V*** and ***W-N***; PS operator *LAB* setcolor*



Picture D5w: Script and Landolt-rings ***N, O, L*** and ***V***; PS operator *LAB* setcolor*



Picture D6w: Landolt-rings ***W-O*** and ***W-L***; PS operator *LAB* setcolor*



Picture D7w: Landolt-rings ***W-V*** and ***W-N***; PS operator *LAB* setcolor*

Test chart LE32: 16 CIELAB steps of ISO/IEC 15775
Chromatic−White, Chromatic−Black, Black−White

input(TLS00): *LAB* setcolor*
output(TLS00): *no change compared to input*