used coordinate squares

V	LAB^*_{TLS00}
M	LAB^*_{TLS00}
O	LAB^*_{TLS00}
Y	LAB^*_{TLS00}
L	LAB^*_{TLS00}
C	LAB^*_{TLS00}
Mw	LAB^*_{TLS00}
Yw	LAB^*_{TLS00}
Cw	LAB^*_{TLS00}
Mn	LAB^*_{TLS00}
Yn	LAB^*_{TLS00}
Cn	LAB^*_{TLS00}
W	LAB^*_{TLS00}
N	LAB^*_{TLS00}

16 equidistant CIELAB steps in *LAB*(TLS00)* for colour series *C−V, V−M, M−O, O−Y, Y−L, L−C, N−W, W−N, Cw−Mw, Mw−Yw, Yw−Cw, Cn−Mn, Mn−Yn, Yn−Cn* and 14 CIE-test colours (left)

Test chart LE72: 16 CIELAB steps in *LAB** Maximum and half (47%) chroma, CIE−test colours

input,ORS18: *LAB* setcolor*
output,ORS18: *Startup (S) data dependend*

See for similar files: http://www.ps.bam.de/LE72/LE72.HTM
Information and Order: http://www.ps.bam.de Version 2.0, io=5,0?

BAM registration: 20030101-LE72/10S/S72E06SP.PS/.PDF
application for measurement of monitor (Yr=2.5) and printer output

BAM material: code=rha4ta