See for similar files: http://www.ps.bam.de/XE12/; www.ps.bam.de/XE.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1

BAM registration: 20080101-XE12/10L/L12E00NA.PS/.TXT BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems



BAM-test chart XE12; Colorimetric systems, ORS18, Page 5
9 step standard colour scales, coordinate transformations

input: *000n / w / nnn0 / rgb set...*
output: *−>cmyn5* setcmyk..*