

AE890−7N, 1/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=0%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



TUB-test chart AE89; 1080 colours of system G; *Tr*=0%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



AE890−7N, 3/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=2,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change





AE890−7N, 5/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



TUB-test chart AE89; 1080 colours of system G; *Tr*=5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



AE890−7N, 7/16

see similar files: http://farbe.li.tu-berlin.de/AE89/AE89.HTM
technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TUB registration: 20160501-AE89/AE89L0NP.PDF /.PS
application for measurement of printer or monitor systems

TUB material: code=rha4ta

TUB-test chart AE89; 1080 colours of system G; *Tr*=7,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



TUB-test chart AE89; 1080 colours of system G; *Tr*=7,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



AE890−7N, 9/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=10%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



AE890−7N, 10/16



AE890−7N, 11/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=12,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



TUB-test chart AE89; 1080 colours of system G; *Tr*=12,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



AE890−7N, 13/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=15%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



TUB-test chart AE89; 1080 colours of system G; *Tr*=15%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



AE890−7N, 15/16

TUB-test chart AE89; 1080 colours of system G; *Tr*=17,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change



TUB-test chart AE89; 1080 colours of system G; *Tr*=17,5%, (Fadin)
Change of white to gray for sRGB display produces luminous colours

input: *rgb setrgbcolor*
output: no change