www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−1; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−2; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−3; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−4; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input



Fe28−5, olv* CaSgx=1 colorm=1 scharm=0 schanv=4 DIEmp=0, (A−a, k−n), DIEmp=1, (b−j)

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−6; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−7; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−8; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 1/6; start output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/; www.ps.bam.de/fe-ultM
Technical information: http://www.ps.bam.de/

Version 2.1, ie= 1.1, CIELAB, GoSgx=0

BAM-registration: 20081003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems

BAM material: code=ubaba

Fe28−9; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb−>olv* setrgbcolor*
output: no change compared to input

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1 ie= 1.1, CIELAB, GoSgx=0

BAM-registrant: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba

Fe28-1, Picture B4: 16 equidistant steps W=C, W=M, W=Y, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture B5: 16 equidistant steps W=C, W=M, W=Y, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture B6: 16 equidistant steps W=C, W=M, W=Y, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture B7: 16 equidistant steps W=C, W=M, W=Y, W=N; PS operator ob* setrgbcolor

Fe28-3, Picture B3: Radial gratings W=C, W=M, W=Y, W=N, W=Z; PS operator ob* setrgbcolor

Fe28-3, Picture B5: Script and Landolt-rings N, C, M, Y, Z; PS operator ob* setrgbcolor

Fe28-3, Picture B6: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-3, Picture B7: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B3N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B5N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B6N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B7N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-7, Picture B3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator ob* setrgbcolor

Fe28-7, Picture B7: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-7, Picture B7N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28–1; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb*->olv** setrgbcolor
output: *->LAB*->cmyn6* setcmyk

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Fe28-1, Picture B4: 16 equidistant steps W=C, W=M, W=Y, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture B5: 16 equidistant steps W=C, W=M, W=Y, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture B6: 16 equidistant steps Z=C, Z=M, Z=Y, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture B7: 16 equidistant steps Z=C, Z=M, Z=Y, W=N; PS operator ob* setrgbcolor

Fe28-3, Picture B3: Radial gratings W=C, W=M, W=Y, W=N, W=Z; PS operator ob* setrgbcolor

Fe28-3, Picture B5: Script and Landolt-rings W, C, M, Y, Z; PS operator ob* setrgbcolor

Fe28-3, Picture B6: Script and Landolt-rings N, C, M, Y, W; PS operator ob* setrgbcolor

Fe28-3, Picture B7: Script and Landolt-rings N, C, M, Y, W; PS operator ob* setrgbcolor

Fe28-5, Picture B3N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B5N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B6N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-5, Picture B7N: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-7, Picture B3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator ob* setrgbcolor

Fe28-7, Picture B7: Landolt-rings W=C, W=M; PS operator ob* setrgbcolor

Fe28-7, Picture B7N: Landolt-rings N, W=C, W=M; PS operator ob* setrgbcolor

Fe28–2; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb*->olv** setrgbcolor
output: *->LAB*->cmyn6* setcmyk

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Fe28-1, Picture D4: 16 equidistant steps W=O, W=L, W=V, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture D5: 16 equidistant steps W=O, W=L, W=V, W=N; PS operator ob* setrgbcolor

Fe28-3, Picture D3: Radial gratings W=O, W=L, W=V, W=N, W=Z; PS operator ob* setrgbcolor

Fe28-3, Picture D5: Script and Landolt-rings N, O, L, V, Z; PS operator ob* setrgbcolor

Fe28-5, Picture D3N: Landolt-rings W=O, W=L; PS operator ob* setrgbcolor

Fe28-5, Picture D5N: Landolt-rings W=O, W=L; PS operator ob* setrgbcolor

Fe28-7, Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator ob* setrgbcolor

Fe28-7, Picture D7: Landolt-rings W=L, W=N; PS operator ob* setrgbcolor

Fe28–3; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb*->olv** setrgbcolor
output: *->LAB*->cmyn6* setcmyk

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Fe28-1, Picture D4N: 16 equidistant steps W=O, W=L, W=V, W=N; PS operator ob* setrgbcolor

Fe28-1, Picture D5N: 16 equidistant steps W=O, W=L, W=V, W=N; PS operator ob* setrgbcolor

Fe28-3, Picture D3N: Landolt-rings W=O, W=L; PS operator ob* setrgbcolor

Fe28-3, Picture D5N: Landolt-rings W=O, W=L; PS operator ob* setrgbcolor

Fe28-5, Picture D3N: Landolt-rings W=O, W=L; PS operator ob* setrgbcolor

Fe28-5, Picture D5N: Landolt-rings W=O, W=L; PS operator ob* setrgbcolor

Fe28-7, Picture D3N: Landolt-rings N, W=O, W=L; PS operator ob* setrgbcolor

Fe28-7, Picture D7N: Landolt-rings N, W=L, W=N; PS operator ob* setrgbcolor

Fe28–4; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb*->olv** setrgbcolor
output: *->LAB*->cmyn6* setcmyk

Fe28–5, olv* CaSpu=1 column=1 scharm=1 schann=4 DIEmp=0, (A-a, k-n), DIEmp=1, (b-j)

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Fe28-1, Picture B4: 16 equidistant steps W=C, W=M, W=J, W=N; PS operator rgb* setrgbcolor

Fe28-1, Picture B5: 16 equidistant steps W=C, W=M, W=J, W=N; PS operator rgb* setrgbcolor

Fe28-1, Picture B6: 16 equidistant steps Z=C, Z=M, Z=J, W=N; PS operator rgb* setrgbcolor

Fe28-1, Picture B7: 16 equidistant steps Z=C, Z=M, Z=J, W=N; PS operator rgb* setrgbcolor

Fe28-3, Picture B3: Radial gratings W=C, W=M, W=J, W=N, W=Z; PS operator rgb* setrgbcolor

Fe28-3, Picture B5: Script and Landolt-rings W, C, M', J, Z; PS operator rgb* setrgbcolor

Fe28-3, Picture B6: Script and Landolt-rings N, C', M', J; PS operator rgb* setrgbcolor

Fe28-3, Picture B7: Script and Landolt-rings N, C', M', J; PS operator rgb* setrgbcolor

Fe28-5, Picture B3N: Landolt-rings W=C', W=M'; PS operator rgb* setrgbcolor

Fe28-5, Picture B5N: Landolt-rings W=C', W=M'; PS operator rgb* setrgbcolor

Fe28-5, Picture B6N: Landolt-rings W=C', W=M'; PS operator rgb* setrgbcolor

Fe28-5, Picture B7N: Landolt-rings W=C', W=M'; PS operator rgb* setrgbcolor

Fe28-7, Picture B3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator rgb* setrgbcolor

Fe28-7, Picture B7: Landolt-rings W=C', W=M'; PS operator rgb* setrgbcolor

Fe28-7, Picture B7N: Landolt-rings N, W=C', W=M'; PS operator rgb* setrgbcolor

Fe28–7; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, *rgb** interpretation
input: *rgb*->rgb* setrgbcolor
output: *->LAB*->cmyn6* setcmyk

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Fe28-1, Picture D4: 16 equidistant steps W=R, W=G, W=B, W=N; PS operator rgb* setrgbcolor

Fe28-1, Picture D5: 16 equidistant steps W=R, W=G, W=B, W=N; PS operator rgb* setrgbcolor

Fe28-3, Picture D3: Radial gratings W=R, W=G, W=B, W=N, W=Z; PS operator rgb* setrgbcolor

Fe28-3, Picture D5: Script and Landolt-rings N, R, G, B, Z; PS operator rgb* setrgbcolor

Fe28-5, Picture D3N: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28-5, Picture D5N: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28-7, Picture D3: 14 CIE-test colours and 2 + 16 grey steps; Use of PS operator rgb* setrgbcolor

Fe28-7, Picture D7: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28–8; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, *rgb** interpretation
input: *rgb*->rgb* setrgbcolor
output: *->LAB*->cmyn6* setcmyk

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 2/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F)

Fe28-1, Picture D4: 16 equidistant steps W=R, W=G, W=B, W=N; PS operator rgb* setrgbcolor

Fe28-1, Picture D5: 16 equidistant steps W=R, W=G, W=B, W=N; PS operator rgb* setrgbcolor

Fe28-3, Picture D3N: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28-3, Picture D5N: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28-5, Picture D3N: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28-5, Picture D5N: Landolt-rings W=R, W=G; PS operator rgb* setrgbcolor

Fe28-7, Picture D3N: Landolt-rings N=R, W=G; PS operator rgb* setrgbcolor

Fe28-7, Picture D7N: Landolt-rings N=R, W=G; PS operator rgb* setrgbcolor

Fe28–9; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, *rgb** interpretation
input: *rgb*->rgb* setrgbcolor
output: *->LAB*->cmyn6* setcmyk


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: c n*
Fe28–1; Picture B4: 16 equidistant steps W-C, W-M, W-Y, W-N; PS operator ob* setrgbcolor
Fe28–3; Picture B5: Script and Landolt-rings N, C, M, Y, Z; PS operator ob* setrgbcolor
Fe28–1; Picture B2: Radial grating W-C, W-M, W-Y, W-N, W-Z; PS operator ob* setrgbcolor
Fe28–5; Picture B6: Landolt-rings W-C, W-M; PS operator ob* setrgbcolor
Fe28–7; Picture B3: 14 CIE-test colours and 2 × 16 grey steps; Use of PS operator ob* setrgbcolor
Fe28–7; Picture B7: Landolt-rings W-Y, W-N; PS operator ob* setrgbcolor
Fe28–2; Picture B1: 16 equidistant steps W-C, W-M, W-Y, W-N; PS operator ob* setrgbcolor
Fe28–4; Picture B8: Landolt-rings W-C, W-M, W-Y, W-N; PS operator ob* setrgbcolor
Fe28–1; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: c n*
Fe28–1; Picture B4: 16 equidistant steps W-C, W-M, W-Y, W-N; PS operator ob* setrgbcolor
Fe28–3; Picture B5: Script and Landolt-rings N, C, M, Y, Z; PS operator ob* setrgbcolor
Fe28–1; Picture B6: 16 equidistant steps Z-C, Z-M, Z-Y, W-N; PS operator ob* setrgbcolor
Fe28–3; Picture B7: Script and Landolt-rings N, C, M, Y, W; PS operator ob* setrgbcolor
Fe28–5; Picture B8N: Landolt-rings W-C, W-N; PS operator ob* setrgbcolor
Fe28–5; Picture B8Z: Landolt-rings Z-C, Z-M; PS operator ob* setrgbcolor
Fe28–7; Picture B3: 14 CIE-test colours and 2 × 16 grey steps; Use of PS operator ob* setrgbcolor
Fe28–7; Picture B7N: Landolt-rings N-Y, W-N; PS operator ob* setrgbcolor
Fe28–7; Picture B7Z: Landolt-rings Z-Y, W-N; PS operator ob* setrgbcolor
Fe28–2; Picture B1: 16 equidistant steps W-C, W-M, W-Y, W-N; PS operator ob* setrgbcolor
Fe28–4; Picture B8: Landolt-rings W-C, W-M, W-Y, W-N; PS operator ob* setrgbcolor
Fe28–2; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: c n*
Fe28–1; Picture D4: 16 equidistant steps W-O, W-L, W-V, W-N; PS operator ob* setrgbcolor
Fe28–3; Picture D5: Script and Landolt-rings N, O, L, V, Z; PS operator ob* setrgbcolor
Fe28–1; Picture D2: Radial grating W-O, W-L, W-V, W-N, W-Z; PS operator ob* setrgbcolor
Fe28–5; Picture D6: Landolt-rings W-O, W-L; PS operator ob* setrgbcolor
Fe28–7; Picture D3: 14 CIE-test colours and 2 × 16 grey steps; Use of PS operator ob* setrgbcolor
Fe28–7; Picture D7: Landolt-rings W-V, W-N; PS operator ob* setrgbcolor
Fe28–3; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: c n*
Fe28–1; Picture D4N: 16 equidistant steps W-O, W-L, W-V, W-N; PS operator ob* setrgbcolor
Fe28–1; Picture D4Z: 16 equidistant steps Z-O, Z-L, Z-V, W-N; PS operator ob* setrgbcolor
Fe28–3; Picture D5N: Script and Landolt-rings W, O, L, V; PS operator ob* setrgbcolor
Fe28–3; Picture D5Z: Script and Landolt-rings N, O, L, V; W; PS operator ob* setrgbcolor
Fe28–5; Picture D6N: Landolt-rings W-O, W-L; PS operator ob* setrgbcolor
Fe28–5; Picture D6Z: Landolt-rings Z-O, Z-L; PS operator ob* setrgbcolor
Fe28–7; Picture D7N: Landolt-rings N-V, W-N; PS operator ob* setrgbcolor
Fe28–7; Picture D7Z: Landolt-rings Z-V, W-N; PS operator ob* setrgbcolor
Fe28–4; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba




www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: cm n*
Fe28–1; Picture B4: 16 equidistant steps W-C, W-M, W-J, W-N; PS operator rgb* setrgbcolor
Fe28–3; Picture D5: Script and Landolt-rings N, R, G, B, Z; PS operator rgb* setrgbcolor
Fe28–1; Picture B2: Radial grating W-C, W-M, W-J, W-N, W-Z; PS operator rgb* setrgbcolor
Fe28–5; Picture B6: Landolt-rings W-C, W-M; PS operator rgb* setrgbcolor
Fe28–7; Picture B3: 14 CIE-test colours and 2 × 16 grey steps; Use of PS operator rgb* setrgbcolor
Fe28–7; Picture B7: Landolt-rings W-J, W-N; PS operator rgb* setrgbcolor
Fe28–6; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: cm n*
Fe28–1; Picture B4N: 16 equidistant steps W-C, A-M, W-J, W-N; PS operator rgb* setrgbcolor
Fe28–1; Picture B4Z: 16 equidistant steps Z-C, Z-M, Z-J, W-N; PS operator rgb* setrgbcolor
Fe28–3; Picture B5N: Script and Landolt-rings W, C, M', J, Z; PS operator rgb* setrgbcolor
Fe28–3; Picture B5Z: Script and Landolt-rings N, C', M', J, W; PS operator rgb* setrgbcolor
Fe28–5; Picture B6N: Landolt-rings W-C', W-M'; PS operator rgb* setrgbcolor
Fe28–5; Picture B6Z: Landolt-rings Z-C', Z-M'; PS operator rgb* setrgbcolor
Fe28–7; Picture B7N: Landolt-rings N-J, W-N; PS operator rgb* setrgbcolor
Fe28–7; Picture B7Z: Landolt-rings Z-J, W-N; PS operator rgb* setrgbcolor
Fe28–7; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: cm n*
Fe28–1; Picture D4: 16 equidistant steps W-R, W-G, W-B, W-N; PS operator rgb* setrgbcolor
Fe28–3; Picture D5: Script and Landolt-rings N, R, G, B, Z; PS operator rgb* setrgbcolor
Fe28–1; Picture B2: Radial grating W-R, W-G, W-B, W-N, W-Z; PS operator rgb* setrgbcolor
Fe28–5; Picture D6: Landolt-rings W-R, W-G; PS operator rgb* setrgbcolor
Fe28–7; Picture D3: 14 CIE-test colours and 2 × 16 grey steps; Use of PS operator rgb* setrgbcolor
Fe28–7; Picture D7: Landolt-rings W-B, W-N; PS operator rgb* setrgbcolor
Fe28–8; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 3/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: cm n*
Fe28–1; Picture D4: 16 equidistant steps W-R, W-G, A-B, W-N; PS operator rgb* setrgbcolor
Fe28–3; Picture D5: Script and Landolt-rings W, R, G, B, Z; PS operator rgb* setrgbcolor
Fe28–1; Picture D4N: 16 equidistant steps W-R, W-G, A-B, W-N; PS operator rgb* setrgbcolor
Fe28–1; Picture D4Z: 16 equidistant steps Z-R, Z-G, Z-B, W-N; PS operator rgb* setrgbcolor
Fe28–3; Picture D5N: Script and Landolt-rings W, R, G, B; PS operator rgb* setrgbcolor
Fe28–3; Picture D5Z: Script and Landolt-rings N, R, G, B; W; PS operator rgb* setrgbcolor
Fe28–5; Picture D6N: Landolt-rings W-R, W-G; PS operator rgb* setrgbcolor
Fe28–5; Picture D6Z: Landolt-rings Z-R, Z-G; PS operator rgb* setrgbcolor
Fe28–7; Picture D7N: Landolt-rings W-B, W-N; PS operator rgb* setrgbcolor
Fe28–7; Picture D7Z: Landolt-rings Z-B, W-N; PS operator rgb* setrgbcolor
Fe28–9; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
Set for similar files: http://www.ps.bam.de/Fe28/ www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF
Technical information: http://www.ps.bam.de/ Version 2.1, ie= 1.1, CIELAB, GoSgx=0
BAM-registration: 20/08/003-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM-material: code=ubaba

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–1; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb*->olv* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–2; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, *olv** interpretation
input: *rgb->olv* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–3; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb->olv* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–4; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, *olv** interpretation
input: *rgb->olv* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–5; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, *rgb** interpretation
input: *rgb->rgb* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–6; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, *rgb** interpretation
input: *rgb->rgb* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–7; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, *rgb** interpretation
input: *rgb->rgb* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–8; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, *rgb** interpretation
input: *rgb->rgb* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 4/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: m n*

Fe28–9; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, *rgb** interpretation
input: *rgb->rgb* setrgbcolor*
output: *->LAB*->cmyn6* setcmyk*

Set for similar files: http://www.ps.bam.de/Fe28/ - www.ps.bam.de/Fe28/10L/L28E00FP.PS/ - PDF
Technical information: http://www.ps.bam.de/ Version 2.1 ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080403-Fe28/10L/L28E00FP.PS/ - PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–1; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–2; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–3; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–4; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, olv* interpretation
input: rgb~>olv* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba




www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–6; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B1 to B7 similar ISO/IEC-Test chart 2, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–7; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-Test chart 2, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–8; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D1 to D7 similar ISO/IEC-Test chart 4, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba


www.ps.bam.de/Fe28/10L/L28E00FP.PS/ .PDF, Page 5/6; linearized output
F: linearized outputFe28/10L/L28E00FP.DAT in File (F); Separation: yn*
Fe28–9; Test elements of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. D4 to D7 similar ISO/IEC-Test chart 4, rgb* interpretation
input: rgb~>rgb* setrgbcolor
output: ~>LAB*~>cmyn6* setcmyk
See for similar files: http://www.bam.de/Fe28/: www.ps.bam.de/Fe-HTM
Technical information: http://www.ps.bam.de/
Version 2.1, ie=1.1, CIELAB, GoSgx=0
BAM-registration: 20080103-Fe28/10L/L28E00FP.PS/ .PDF
application for evaluation and measurement of printer or monitor systems
BAM material: code=ubaba