See for similar files: http://www.ps.bam.de/FE95/FE95.HTM
Information and Order: http://www.ps.bam.de   Version 2.0; io=5,5; iORS; oORS, CIELAB

BAM registration: 20030101-FE95/10Q/Q95E05FP.PS/.PDF

application for measurement of monitor (Yr=2.5) and printer output

BAM material: code=rha4ta

C LAB*

M LAB*

Y LAB*

N LAB*

O LAB*

L LAB*

V LAB*

N LAB*

| 0 | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | A | B | C | D | E | F |

Figure B4 and D4 of the ISO/IEC-test charts no. 2 and 4; 16 visual equidistant steps of colour series; Use of the PS operator *LAB* setcolor

Fig. B4 of ISO/IEC-test chart 2 and   ISO/IEC 15775 and   input: *LAB* setcolor
Fig. D4 of ISO/IEC-test chart no. 4;   TR ISO/IEC 24705;   output: *LAB* setcolor