

Fe010−1, Picture B4N: 16 equidistant steps ***N−C, N−M, N−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe010−3, Picture B5N: Script and Landolt-rings ***W, C, M, Y, Z;*** *PS* operator *olv* setrgbcolor*



Fe010−5, Picture B6N: Landolt-rings ***N−C, N−M;*** *PS* operator *olv* setrgbcolor*



Fe010−7, Picture B7N: Landolt-rings ***N−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe011−1, Picture B4Z: 16 equidistant steps ***Z−C, Z−M, Z−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe011−3, Picture B5Z: Script and Landolt-rings ***N, C, M, Y, W;*** *PS* operator *olv* setrgbcolor*



Fe011−5, Picture B6Z: Landolt-rings ***Z−C, Z−M;*** *PS* operator *olv* setrgbcolor*



Fe011−7, Picture B7Z: Landolt-rings ***Z−Y, W−N;*** *PS* operator *olv* setrgbcolor*

See for similar files: http://www.ps.bam.de/Fe01/; www.ps.bam.de/Fe.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, ColSpx=1

BAM registration: 20080901-Fe01/10L/L01E00NP.PS/ .PDF BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems

See for similar files: http://www.ps.bam.de/Fe01/; www.ps.bam.de/Fe.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, ColSpx=1

BAM registration: 20080901-Fe01/10L/L01E00NP.PS/ .PDF BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems



Fe010−1, Picture B4N: 16 equidistant steps ***N−C, N−M, N−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe010−3, Picture B5N: Script and Landolt-rings ***W, C, M, Y, Z;*** *PS* operator *olv* setrgbcolor*



Fe010−5, Picture B6N: Landolt-rings ***N−C, N−M;*** *PS* operator *olv* setrgbcolor*



Fe010−7, Picture B7N: Landolt-rings ***N−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe011−1, Picture B4Z: 16 equidistant steps ***Z−C, Z−M, Z−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe011−3, Picture B5Z: Script and Landolt-rings ***N, C, M, Y, W;*** *PS* operator *olv* setrgbcolor*



Fe011−5, Picture B6Z: Landolt-rings ***Z−C, Z−M;*** *PS* operator *olv* setrgbcolor*



Fe011−7, Picture B7Z: Landolt-rings ***Z−Y, W−N;*** *PS* operator *olv* setrgbcolor*

Fe01; Test chart of ISO/IEC 15775 and ISO/IEC TR 24705
Fig. B4 to B7 similar ISO/IEC-test chart 2, *olv** interpretation

input: *rgb−>olv* setrgbcolor*
output: *olv*−>cmyn6* setcmyk*

BAM registration: 20080901-Fe01/10L/L01E00NP.PS/ .PDF BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems

See for similar files: http://www.ps.bam.de/Fe01/; www.ps.bam.de/Fe.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, ColSpx=1

BAM registration: 20080901-Fe01/10L/L01E00NP.PS/ .PDF BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems

See for similar files: http://www.ps.bam.de/Fe01/; www.ps.bam.de/Fe.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, ColSpx=1

BAM registration: 20080901-Fe01/10L/L01E00NP.PS/ .PDF BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems

See for similar files: http://www.ps.bam.de/Fe01/; www.ps.bam.de/Fe.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, ColSpx=1

See for similar files: http://www.ps.bam.de/Fe01/; www.ps.bam.de/Fe.HTM
Technical information: http://www.ps.bam.de Version 2.1, io=1,1, ColSpx=1

BAM registration: 20080901-Fe01/10L/L01E00NP.PS/ .PDF BAM material: code=rha4ta
application for evaluation and measurement of printer or monitor systems



Fe010−1, Picture B4N: 16 equidistant steps ***N−C, N−M, N−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe011−1, Picture B4Z: 16 equidistant steps ***Z−C, Z−M, Z−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe010−3, Picture B5N: Script and Landolt-rings ***W, C, M, Y, Z;*** *PS* operator *olv* setrgbcolor*



Fe011−3, Picture B5Z: Script and Landolt-rings ***N, C, M, Y, W;*** *PS* operator *olv* setrgbcolor*



Fe010−5, Picture B6N: Landolt-rings ***N−C, N−M;*** *PS* operator *olv* setrgbcolor*



Fe011−5, Picture B6Z: Landolt-rings ***Z−C, Z−M;*** *PS* operator *olv* setrgbcolor*



Fe010−7, Picture B7N: Landolt-rings ***N−Y, W−N;*** *PS* operator *olv* setrgbcolor*



Fe011−7, Picture B7Z: Landolt-rings ***Z−Y, W−N;*** *PS* operator *olv* setrgbcolor*