

See for similar files: <http://www.ps.bam.de/LE12/LE12.HTM>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=0,0

used coordinate squares

LAB^{*}_{TLS00}

C
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

M
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

Y
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

O
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

L
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

V
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

N/W
LAB^{*}_{TLS00}

LAB^{*}_{TLS00}

BAM registration: 20030101-LE12/10Q/Q12E03NP.PS/.PDF BAM material: code=rha4ta
application for measurement of monitor (Yr=2.5) and printer output

16 equidistant CIELAB steps: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W, W-N and 14 CIE-test colours (left)

Test chart LE12: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White

input ,TLS00: *LAB*^{*} *setcolor/cmy*^{*} *setcmyk*^{..}
output ,TLS00: *no change compared to input*