

Siehe ähnliche Dateien: <http://www.ps.bam.de/LG07/LG07.HTM>
Information, Bestellung: <http://www.ps.bam.de> Version 2.0, io=0,2; iORS; oORS, CIELAB

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	Benutzte Koordinate Umfeld Infeld
01																		<i>o11*</i> <i>LAB*</i> _{ORS18}
02																		C <i>o1v*</i> <i>LAB*</i> _{ORS18}
03																		<i>111*</i> <i>LAB*</i> _{ORS18}
04																		M <i>o0v*</i> <i>LAB*</i> _{ORS18}
05																		<i>11v*</i> <i>LAB*</i> _{ORS18}
06																		Y <i>o10*</i> <i>LAB*</i> _{ORS18}
07																		<i>11v*</i> <i>LAB*</i> _{ORS18}
08																		O <i>o00*</i> <i>LAB*</i> _{ORS18}
09																		<i>o1v*</i> <i>LAB*</i> _{ORS18}
10																		L <i>o10*</i> <i>LAB*</i> _{ORS18}
11																		<i>o11*</i> <i>LAB*</i> _{ORS18}
12																		V <i>o0v*</i> <i>LAB*</i> _{ORS18}
13																		<i>o1v*</i> <i>LAB*</i> _{ORS18}
14																		N/W <i>w*</i> <i>LAB*</i> _{ORS18}

16 gleichabständige CIELAB-Stufen: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W, W-N und 14 CIE-Testfarben (links)

Prüfvorlage LG07: CIELAB-Stufen ISO/IEC 15775
Bunt-Weiß, Bunt-Schwarz, Schwarz-Weiß

Eingabe(ORS18): *olv* setrgb../LAB* setcolor*
Ausgabe(ORS18): *cmv0* /nnn0* setcmvcolor*

BAM-Registrierung: 20030101-LG07/10L/L07G02FP.PS/.PDF BAM-Material: Code=rha4ta
Anwendung für Messung von Monitor- (Yr=2.5) und Druckerausgabe