

Siehe ähnliche Dateien: <http://www.ps.bam.de/LG69/LG69.HTM>
Information, Bestellung: <http://www.ps.bam.de> Version 2.0, io=5&1,5&1

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	Benutzte Koordinate
01																		<i>V</i> $LAB^*_{ORS18} 0/1^*$
02																		<i>M</i> $LAB^*_{ORS18} 001^*$
03																		<i>O</i> $LAB^*_{ORS18} 10v^*$
04																		<i>Y</i> $LAB^*_{ORS18} 110^*$
05																		<i>L</i> $LAB^*_{ORS18} 010^*$
06																		<i>C</i> $LAB^*_{ORS18} 01v^*$
07																		<i>Mw</i> $LAB^*_{ORS18} x/1^*$
08																		<i>Yw</i> $LAB^*_{ORS18} 0x1^*$
09																		<i>Cw</i> $LAB^*_{ORS18} 1xv^*$
10																		<i>Mn</i> $LAB^*_{ORS18} x/0^*$
11																		<i>Yn</i> $LAB^*_{ORS18} 0x0^*$
12																		<i>Cn</i> $LAB^*_{ORS18} 0xv^*$
13																		<i>W</i> $LAB^*_{ORS18} 0lv^*$
14																		<i>N</i> $LAB^*_{ORS18} w^*$

BAM-Registrierung: 20030101-LG69/10Q/Q69G04NP.PS/.PDF BAM-Material: Code=rha4ta
Anwendung für Messung von Monitor- (Yr=2.5) und Druckerausgabe