


See for similar files: <http://www.ps.bam.de/ZE48/>; www.ps.bam.de/ZE48/10L/L48E00FP.PS/.PDF
Technical information: <http://www.ps.bam.de> Version 2.1, io=1,1, CIELAB

BAM registration: 20071001-ZE48/10L/L48E00FP.PS/.PDF BAM material: code=rh4ta
application for evaluation and measurement of printer or monitor systems



ZE480-7F, Test chart with 40x27=1080 colours; digital equidistant 9 or 16 step colour scales; Colour data in column (A-n): rgb (A-j, n), 000n (k), w (l), nnn0 (m), 5,4mm x 5,4mm, Page 1/6, ORS18

BAM-test chart ZE48; Colorimetric systems, Page 1/6


input: 000n / w / nnn0 / rgb set...

40x27=1080 colours for Measurement: rgb / w / cmy0 / 000n output: no change compared to input

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z	a	b	c	d	e	f	g	h	i	j	k	l	m	n
01	0000 A01 0.0 0.125 0.0	0009 B01 0.0 0.125 0.0	0018 C01 0.0 0.125 0.0	0027 D01 0.0 0.125 0.0	0036 E01 0.0 0.125 0.0	0045 F01 0.0 0.125 0.0	0054 G01 0.0 0.125 0.0	0063 H01 0.0 0.125 0.0	0072 I01 0.0 0.125 0.0	0081 J01 0.0 0.125 0.0	0090 K01 0.0 0.125 0.0	0099 L01 0.0 0.125 0.0	0108 M01 0.0 0.125 0.0	0117 N01 0.0 0.125 0.0	0126 O01 0.0 0.125 0.0	0135 P01 0.0 0.125 0.0	0144 Q01 0.0 0.125 0.0	0153 R01 0.0 0.125 0.0	0162 S01 0.0 0.125 0.0	0171 T01 0.0 0.125 0.0	0180 U01 0.0 0.125 0.0	0189 V01 0.0 0.125 0.0	0198 W01 0.0 0.125 0.0	0207 X01 0.0 0.125 0.0	0216 Y01 0.0 0.125 0.0	0225 Z01 0.0 0.125 0.0	0234 a01 0.0 0.125 0.0	729 b01 1.0 0.875 1.0	738 c01 1.0 0.875 1.0	747 d01 1.0 0.875 1.0	756 e01 1.0 0.875 1.0	765 f01 1.0 0.875 1.0	774 g01 1.0 0.875 1.0	783 h01 1.0 0.875 1.0	792 i01 1.0 0.875 1.0	801 j01 1.0 0.875 1.0	0972 k01 n=1.0 0000+ w=0.0	0981 l01 n=1.0 0000+ w=0.0	0990 m01 n=1.0 0000+ w=0.0	0999 n01 n=1.0 0000+ w=0.0
02	0001 A02 0.0 0.125 0.125	0010 B02 0.0 0.125 0.125	0019 C02 0.0 0.125 0.125	0028 D02 0.0 0.125 0.125	0037 E02 0.0 0.125 0.125	0046 F02 0.0 0.125 0.125	0055 G02 0.0 0.125 0.125	0064 H02 0.0 0.125 0.125	0073 I02 0.0 0.125 0.125	0082 J02 0.0 0.125 0.125	0091 K02 0.0 0.125 0.125	0100 L02 0.0 0.125 0.125	0109 M02 0.0 0.125 0.125	0118 N02 0.0 0.125 0.125	0127 O02 0.0 0.125 0.125	0136 P02 0.0 0.125 0.125	0145 Q02 0.0 0.125 0.125	0154 R02 0.0 0.125 0.125	0163 S02 0.0 0.125 0.125	0172 T02 0.0 0.125 0.125	0181 U02 0.0 0.125 0.125	0190 V02 0.0 0.125 0.125	0199 W02 0.0 0.125 0.125	0208 X02 0.0 0.125 0.125	0217 Y02 0.0 0.125 0.125	0226 Z02 0.0 0.125 0.125	0235 a02 0.0 0.125 0.125	730 b02 0.875 0.875 0.875	739 c02 0.875 0.875 0.875	748 d02 0.875 0.875 0.875	757 e02 0.875 0.875 0.875	766 f02 0.875 0.875 0.875	775 g02 0.875 0.875 0.875	784 h02 0.875 0.875 0.875	793 i02 0.875 0.875 0.875	802 j02 0.875 0.875 0.875	0973 k02 n=0.875 0000+ w=0.125	0982 l02 n=0.875 0000+ w=0.125	0991 m02 n=0.875 0000+ w=0.125	0999 n02 n=0.875 0000+ w=0.125
03	0002 A03 0.0 0.125 0.25	0011 B03 0.0 0.125 0.25	0020 C03 0.0 0.125 0.25	0029 D03 0.0 0.125 0.25	0038 E03 0.0 0.125 0.25	0047 F03 0.0 0.125 0.25	0056 G03 0.0 0.125 0.25	0065 H03 0.0 0.125 0.25	0074 I03 0.0 0.125 0.25	0083 J03 0.0 0.125 0.25	0092 K03 0.0 0.125 0.25	0101 L03 0.0 0.125 0.25	0110 M03 0.0 0.125 0.25	0119 N03 0.0 0.125 0.25	0128 O03 0.0 0.125 0.25	0137 P03 0.0 0.125 0.25	0146 Q03 0.0 0.125 0.25	0155 R03 0.0 0.125 0.25	0164 S03 0.0 0.125 0.25	0173 T03 0.0 0.125 0.25	0182 U03 0.0 0.125 0.25	0191 V03 0.0 0.125 0.25	0200 W03 0.0 0.125 0.25	0209 X03 0.0 0.125 0.25	0218 Y03 0.0 0.125 0.25	0227 Z03 0.0 0.125 0.25	0236 a03 0.0 0.125 0.25	731 b03 1.0 0.875 1.0	740 c03 1.0 0.875 1.0	749 d03 1.0 0.875 1.0	758 e03 1.0 0.875 1.0	767 f03 1.0 0.875 1.0	776 g03 1.0 0.875 1.0	785 h03 1.0 0.875 1.0	794 i03 1.0 0.875 1.0	803 j03 1.0 0.875 1.0	0974 k03 n=0.875 0000+ w=0.125	0983 l03 n=0.875 0000+ w=0.125	0992 m03 n=0.875 0000+ w=0.125	0999 n03 n=0.875 0000+ w=0.125
04	0003 A04 0.0 0.125 0.375	0012 B04 0.0 0.125 0.375	0021 C04 0.0 0.125 0.375	0030 D04 0.0 0.125 0.375	0039 E04 0.0 0.125 0.375	0048 F04 0.0 0.125 0.375	0057 G04 0.0 0.125 0.375	0066 H04 0.0 0.125 0.375	0075 I04 0.0 0.125 0.375	0084 J04 0.0 0.125 0.375	0093 K04 0.0 0.125 0.375	0102 L04 0.0 0.125 0.375	0111 M04 0.0 0.125 0.375	0120 N04 0.0 0.125 0.375	0129 O04 0.0 0.125 0.375	0138 P04 0.0 0.125 0.375	0147 Q04 0.0 0.125 0.375	0156 R04 0.0 0.125 0.375	0165 S04 0.0 0.125 0.375	0174 T04 0.0 0.125 0.375	0183 U04 0.0 0.125 0.375	0192 V04 0.0 0.125 0.375	0201 W04 0.0 0.125 0.375	0210 X04 0.0 0.125 0.375	0219 Y04 0.0 0.125 0.375	0228 Z04 0.0 0.125 0.375	0237 a04 0.0 0.125 0.375	732 b04 1.0 0.875 1.0	741 c04 1.0 0.875 1.0	750 d04 1.0 0.875 1.0	759 e04 1.0 0.875 1.0	768 f04 1.0 0.875 1.0	777 g04 1.0 0.875 1.0	786 h04 1.0 0.875 1.0	795 i04 1.0 0.875 1.0	804 j04 1.0 0.875 1.0	0975 k04 n=0.875 0000+ w=0.125	0984 l04 n=0.875 0000+ w=0.125	0993 m04 n=0.875 0000+ w=0.125	0999 n04 n=0.875 0000+ w=0.125
05	0004 A05 0.0 0.125 0.5	0013 B05 0.0 0.125 0.5	0022 C05 0.0 0.125 0.5	0031 D05 0.0 0.125 0.5	0040 E05 0.0 0.125 0.5	0049 F05 0.0 0.125 0.5	0058 G05 0.0 0.125 0.5	0067 H05 0.0 0.125 0.5	0076 I05 0.0 0.125 0.5	0085 J05 0.0 0.125 0.5	0094 K05 0.0 0.125 0.5	0103 L05 0.0 0.125 0.5	0112 M05 0.0 0.125 0.5	0121 N05 0.0 0.125 0.5	0130 O05 0.0 0.125 0.5	0139 P05 0.0 0.125 0.5	0148 Q05 0.0 0.125 0.5	0157 R05 0.0 0.125 0.5	0166 S05 0.0 0.125 0.5	0175 T05 0.0 0.125 0.5	0184 U05 0.0 0.125 0.5	0193 V05 0.0 0.125 0.5	0202 W05 0.0 0.125 0.5	0211 X05 0.0 0.125 0.5	0220 Y05 0.0 0.125 0.5	0229 Z05 0.0 0.125 0.5	0238 a05 0.0 0.125 0.5	733 b05 1.0 0.875 1.0	742 c05 1.0 0.875 1.0	751 d05 1.0 0.875 1.0	760 e05 1.0 0.875 1.0	769 f05 1.0 0.875 1.0	778 g05 1.0 0.875 1.0	787 h05 1.0 0.875 1.0	796 i05 1.0 0.875 1.0	805 j05 1.0 0.875 1.0	0976 k05 n=0.5 0000+ w=0.5	0985 l05 n=0.5 0000+ w=0.5	0994 m05 n=0.5 0000+ w=0.5	0999 n05 n=0.5 0000+ w=0.5
06	0005 A06 0.0 0.125 0.625	0014 B06 0.0 0.125 0.625	0023 C06 0.0 0.125 0.625	0032 D06 0.0 0.125 0.625	0041 E06 0.0 0.125 0.625	0050 F06 0.0 0.125 0.625	0059 G06 0.0 0.125 0.625	0068 H06 0.0 0.125 0.625	0077 I06 0.0 0.125 0.625	0086 J06 0.0 0.125 0.625	0095 K06 0.0 0.125 0.625	0104 L06 0.0 0.125 0.625	0113 M06 0.0 0.125 0.625	0122 N06 0.0 0.125 0.625	0131 O06 0.0 0.125 0.625	0140 P06 0.0 0.125 0.625	0149 Q06 0.0 0.125 0.625	0158 R06 0.0 0.125 0.625	0167 S06 0.0 0.125 0.625	0176 T06 0.0 0.125 0.625	0185 U06 0.0 0.125 0.625	0194 V06 0.0 0.125 0.625	0203 W06 0.0 0.125 0.625	0212 X06 0.0 0.125 0.625	0221 Y06 0.0 0.125 0.625	0230 Z06 0.0 0.125 0.625	0239 a06 0.0 0.125 0.625	734 b06 1.0 0.875 1.0	743 c06 1.0 0.875 1.0	752 d06 1.0 0.875 1.0	761 e06 1.0 0.875 1.0	770 f06 1.0 0.875 1.0	779 g06 1.0 0.875 1.0	788 h06 1.0 0.875 1.0	797 i06 1.0 0.875 1.0	806 j06 1.0 0.875 1.0	0977 k06 n=0.625 0000+ w=0.625	0986 l06 n=0.625 0000+ w=0.625	0995 m06 n=0.625 0000+ w=0.625	0999 n06 n=0.625 0000+ w=0.625
07	0006 A07 0.0 0.125 0.75	0015 B07 0.0 0.125 0.75	0024 C07 0.0 0.125 0.75	0033 D07 0.0 0.125 0.75	0042 E07 0.0 0.125 0.75	0051 F07 0.0 0.125 0.75	0060 G07 0.0 0.125 0.75	0069 H07 0.0 0.125 0.75	0078 I07 0.0 0.125 0.75	0087 J07 0.0 0.125 0.75	0096 K07 0.0 0.125 0.75	0105 L07 0.0 0.125 0.75	0114 M07 0.0 0.125 0.75	0123 N07 0.0 0.125 0.75	0132 O07 0.0 0.125 0.75	0141 P07 0.0 0.125 0.75	0150 Q07 0.0 0.125 0.75	0159 R07 0.0 0.125 0.75	0168 S07 0.0 0.125 0.75	0177 T07 0.0 0.125 0.75	0186 U07 0.0 0.125 0.75	0195 V07 0.0 0.125 0.75	0204 W07 0.0 0.125 0.75	0213 X07 0.0 0.125 0.75	0222 Y07 0.0 0.125 0.75	0231 Z07 0.0 0.125 0.75	0240 a07 0.0 0.125 0.75	735 b07 1.0 0.875 1.0	744 c07 1.0 0.875 1.0	753 d07 1.0 0.875 1.0	762 e07 1.0 0.875 1.0	771 f07 1.0 0.875 1.0	780 g07 1.0 0.875 1.0	789 h07 1.0 0.875 1.0	798 i07 1.0 0.875 1.0	807 j07 1.0 0.875 1.0	0978 k07 n=0.75 0000+ w=0.75	0987 l07 n=0.75 0000+ w=0.75	0996 m07 n=0.75 0000+ w=0.75	0999 n07 n=0.75 0000+ w=0.75
08	0007 A08 0.0 0.125 0.875	0016 B08 0.0 0.125 0.875	0025 C08 0.0 0.125 0.875	0034 D08 0.0 0.125 0.875	0043 E08 0.0 0.125 0.875	0052 F08 0.0 0.125 0.875	0061 G08 0.0 0.125 0.875	0070 H08 0.0 0.125 0.875	0079 I08 0.0 0.125 0.875	0088 J08 0.0 0.125 0.875	0097 K08 0.0 0.125 0.875	0106 L08 0.0 0.125 0.875	0115 M08 0.0 0.125 0.875	0124 N08 0.0 0.125 0.875	0133 O08 0.0 0.125 0.875	0142 P08 0.0 0.125 0.875	0151 Q08 0.0 0.125 0.875	0160 R08 0.0 0.125 0.875	0169 S08 0.0 0.125 0.875	0178 T08 0.0 0.125 0.875	0187 U08 0.0 0.125 0.875	0196 V08 0.0 0.125 0.875	0205 W08 0.0 0.125 0.875	0214 X08 0.0 0.125 0.875	0223 Y08 0.0 0.125 0.875	0232 Z08 0.0 0.125 0.875	0241 a08 0.0 0.125 0.875	736 b08 1.0 0.875 1.0	745 c08 1.0 0.875 1.0	754 d08 1.0 0.875 1.0	763 e08 1.0 0.875 1.0	772 f08 1.0 0.875 1.0	781 g08 1.0 0.875 1.0	790 h08 1.0 0.875 1.0	799 i08 1.0 0.875 1.0	808 j08 1.0 0.875 1.0	0989 k08 n=0.875 0000+ w=0.875	0998 l08 n=0.875 0000+ w=0.875	0999 m08 n=0.875 0000+ w=0.875	0999 n08 n=0.875 0000+ w=0.875
09	0008 A09 0.0 0.125 1.0	0017 B09 0.0 0.125 1.0	0026 C09 0.0 0.125 1.0	0035 D09 0.0 0.125 1.0	0044 E09 0.0 0.125 1.0	0053 F09 0.0 0.125 1.0	0062 G09 0.0 0.125 1.0	0071 H09 0.0 0.125 1.0	0080 I09 0.0 0.125 1.0	0089 J09 0.0 0.125 1.0	0098 K09 0.0 0.125 1.0	0107 L09 0.0 0.125 1.0	0116 M09 0.0 0.125 1.0	0125 N09 0.0 0.125 1.0	0134 O09 0.0 0.125 1.0	0143 P09 0.0 0.125 1.0	0152 Q09 0.0 0.125 1.0	0161 R09 0.0 0.125 1.0	0170 S09 0.0 0.125 1.0	0179 T09 0.0 0.125 1.0	0188 U09 0.0 0.125 1.0	0197 V09 0.0 0.125 1.0	0206 W09 0.0 0.125 1.0	0215 X09 0.0 0.125 1.0	0224 Y09 0.0 0.125 1.0	0233 Z09 0.0 0.125 1.0	0242 a09 0.0 0.125 1.0	737 b09 1.0 0.875 1.0	746 c09 1.0 0.875 1.0	755 d09 1.0 0.875 1.0	764 e09 1.0 0.875 1.0	773 f09 1.0 0.875 1.0	782 g09 1.0 0.875 1.0	791 h09 1.0 0.875 1.0	800 i09 1.0 0.875 1.0	809 j09 1.0 0.875 1.0	0990 k09 n=1.0 0000+ w=0.0	0999 l09 n=1.0 0000+ w=0.0	0999 m09 n=1.0 0000+ w=0.0	0999 n09 n=1.0 0000+ w=0.0
10	0243 I01 0.375 0.375 0.0	0252 B10 0.375 0.375 0.0	0261 C10 0.375 0.375 0.0	0270 D10 0.375 0.375 0.0	0279 E10 0.375 0.375 0.0	0288 F10 0.375 0.375 0.0	0297 G10 0.375 0.375 0.0	0306 H10 0.375 0.375 0.0	0315 I10 0.375 0.375 0.0	0324 J10 0.375 0.375 0.0	0333 K10 0.375 0.375 0.0	0342 L10 0.375 0.375 0.0	0351 M10 0.375 0.375 0.0	0360 N10 0.375 0.375 0.0	0369 O10 0.375 0.375 0.0	0378 P10 0.375 0.375 0.0	0387 Q10 0.375 0.375 0.0	0396 R10 0.375 0.375 0.0	0405 S10 0.375 0.375 0.0	0414 T10 0.375 0.375 0.0	0423 U10 0.375 0.375 0.0	0432 V10 0.375 0.375 0.0	0441 W10 0.375 0.375 0.0	0450 X10 0.375 0.375 0.0	0459 Y10 0.375 0.375 0.0	0468 Z10 0.375 0.375 0.0	0477 a10 0.375 0.375 0.0	810 b10 1.0 1.0 1.0	819 c10 1.0 1.0 1.0	828 d10 1.0 1.0 1.0	837 e10 1.0 1.0 1.0	846 f10 1.0 1.0 1.0	855 g10 1.0 1.0 1.0	864 h10 1.0 1.0 1.0	873 i10 1.0 1.0 1.0	882 j10 1.0 1.0 1.0	1008 k10 n=1.0 w=0.0	1024 l10 n=1.0 w=0.0	1	

See for similar files: <http://www.ps.bam.de/ZE48/>; www.ps.bam.de/ZE48/10L/L48E00FP.PS/.PDF
Technical information: <http://www.ps.bam.de> Version 2.1, io=1,1, CIELAB

BAM registration: 20071001-ZE48/10L/L48E00FP.PS/.PDF BAM material: code=rh4ta
application for evaluation and measurement of printer or monitor systems



[illegible]

