

HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$\text{P60: } \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 101,79$$

$$x_{\text{F02_X,s}} = 0,3218$$

$$y_{\text{F02_X,s}} = 0,3316$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{l}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P55: \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 102,25$$

$$x_{\text{F02_X,s}} = 0,3327$$

$$y_{\text{F02_X,s}} = 0,3411$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P50: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 102,81$$

$$x_{\text{F02_X,s}} = 0,3461$$

$$y_{\text{F02_X,s}} = 0,3519$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{l}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P45: \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 103,50$$

$$x_{\text{F02_X,s}} = 0,3626$$

$$y_{\text{F02_X,s}} = 0,3641$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P40: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 104,36$$

$$x_{\text{F02_X,s}} = 0,3831$$


$$y_{\text{F02_X,s}} = 0,3775$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$

$$\bar{l}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

B_{1j} 0,2105 0,8550 -0,0396 $\lambda=570$
 P35: $\Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 105,47$
 $x_{\text{F02_X,s}} = 0,4089$
 $y_{\text{F02_X,s}} = 0,3917$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$


$$\bar{I}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P30: \Sigma \bar{I}_{\text{F02_X,s}}(\lambda) = 106,94$$

$$x_{\text{F02_X,s}} = 0,4413$$

$$y_{\text{F02_X,s}} = 0,4052$$



HPE_CIEF02_X cone sensitivity $Y_{\text{sum}}=100$

$$\bar{l}_{\text{F02_X,s}}(\lambda) = B_{11}\bar{x}_{\text{F02_X,s}}(\lambda) + B_{12}\bar{y}_{\text{F02_X,s}}(\lambda) + B_{13}\bar{z}_{\text{F02_X,s}}(\lambda)$$

$$B_{1j} \quad 0,2105 \quad 0,8550 \quad -0,0396 \quad \lambda=570$$

$$P25: \Sigma \bar{l}_{\text{F02_X,s}}(\lambda) = 108,97$$

$$x_{\text{F02_X,s}} = 0,4816$$

$$y_{\text{F02_X,s}} = 0,4147$$

