


5-003130-L0

5-003130-F0

MN521-80, B2\_17




$L^* = 50$

5-013130-L0

5-013130-F0


MN521-81, B2\_17



5-103130-L0

5-103130-F0

MN521-82, B2\_17



$L^* = 50$

5-113130-L0

5-113130-F0

MN521-83, B2\_17