

interfaces in area of:

**color film original – color scanner –
color storage – raster area coverage**

- 1. color scanner with color measurement sensitivities = spectral values**
- 2. minimum 12-Bit color image storage generates cubic screen and quadratic raster area function**
- 3. minimum 8-bit resolution for linear photoelectric sensors**