


<http://130.149.60.45/~farbmetrik/OE68/OE68L0NA.TXT> /.PS; linearized output, Page 1/3
F: Output Linearization (OL) data OE68/OE68L0NA.TXT /.PS in File (F)




OE680-7, Picture B1-130-0: Flower motif, 14 CIE-test colours and 2 + 16 grey steps (sf); PS operators *settransfer*, 3 *colorimage*




OE680-5, Picture D2W-130-0: Radial gratings W-Re; W-Ge; W-Be; W-N; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$




OE680-7, Picture D3W-130-0: 14 CIE-test colours and 2 + 16 grey steps; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$




OE68: Test chart 4 according to ISO 15775, TR 24705; 1MR, DEH input: *rgb* ($\rightarrow \text{rgb}_{de}$) *setrgbcolor*
Image, radial gratings, 16 step colour scales, Landolt-rings
output 130-0: $g_P=1.0$; $g_N=1.0$




OE681-1, Picture D4W-L-130-0: 16 equidistant steps W-Re; W-Ge; W-Be; W-N; PS: $\rightarrow \text{rgb}_e \text{ setrgbcolor}$



OE681-3, Picture D5W-130-0: Script and Landolt-rings N; Re; Ge; Be; Z; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$



OE681-5, Picture D6W-L-130-0: Landolt-rings W-Re; W-Ge; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$



OE681-7, Picture D7W-L-130-0: Landolt-rings W-Be; W-N; PS operator $\rightarrow \text{rgb}_e \text{ setrgbcolor}$

