


$H^*_- = \text{G25B}_-$

HIC*_

$H^*_- = G25B_-$

trekantslyshet T^* 

$$\text{navn} \quad L^* = L_a^* a_a^* \quad b_a^* \quad C_{ab,a}^* \quad h_{ab,a}^*$$

R ₋ Ma	47.9	65.3	50.5	82.6	37
Y ₋ Ma	90.3	-10.2	91.7	92.3	96
G ₋ Ma	50.9	-62.8	34.9	71.9	150
C ₋ Ma	58.6	-30.3	-45.0	54.2	236
B ₋ Ma	25.7	31.0	-44.4	54.2	305
M ₋ Ma	48.1	75.2	-8.3	75.7	353
N ₋ Ma	18.0	0.0	0.0	0.0	0
W ₋ Ma	95.4	0.0	0.0	0.0	0
R ₋ CIE	39.9	58.7	27.9	65.0	25
Y ₋ CIE	81.2	-2.8	71.5	71.6	92
G ₋ CIE	52.2	-42.4	13.6	44.5	162
B ₋ CIE	30.5	1.4	-46.4	46.4	271

LabCh*₋,Ma: 59 -50 -9 51 190

LaSCN ⁻ , M ₁	55	50	5	51	150
HSC ⁺	625B	100	100		

HIC^{*}-,Ma: G25B_100_100-

*rgbic**_{-Ma}:

0.0 1.0 0.5 1.0 1.0

trekantslyshet T^*

%Omfang

$$u^*_{rel} = 92$$

% Regular

$$g^*_{H,rel} = 52$$
$$g^*_{C,rel} = 58$$
$$H^*_- \quad L^* = L^*_a \, a^*_a \quad b^*_a \quad C^*_{ab,a} \, h^*_{ab,a}$$

R00Y_100_100_	48.4	66.1	40.2	77.3	31
R25Y_100_100_	56.8	48.0	50.5	69.6	46
R50Y_100_100_	68.6	25.0	63.9	68.6	68
R75Y_100_100_	80.6	4.8	77.2	77.3	86
Y00G_100_100_	90.2	-9.6	88.2	88.7	96
Y25G_100_100_	83.2	-18.4	79.9	81.9	102
Y50G_100_100_	73.3	-31.7	62.7	70.2	116
Y75G_100_100_	62.0	-49.7	43.2	65.8	139
G00B_100_100_	55.8	-65.2	33.8	73.4	152
G25B_100_100_	59.3	-50.3	-9.0	51.0	190
G50B_100_100_	63.0	-30.5	-42.0	51.9	234
G75B_100_100_	45.7	-5.7	-44.6	44.9	262
B00R_100_100_	27.5	25.9	-47.3	53.9	298
B25R_100_100_	38.3	52.6	-28.5	59.8	331
B50R_100_100_	49.5	73.5	-9.0	74.0	353
B75R_100_100_	48.9	69.3	12.9	70.4	10

