







http://130.149.60.45/~farbmetrik/TE96/TE96L0NP.PDF /.PS; transfer output

N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: http://130.149.60.45/~farbmetrik/TE96/TE96L0NP.PDF /.PS
technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrikTE960-5, Picture B2We: radial gratings W-C_e; W-M_e; W-Y_e; W-N; PS operator: *rgb*->*rgb_e* setrgbcolorTE960-7, Picture B3We: 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator: *rgb/cmy0*->*rgb_e* setrgbcolorTE961-1, Picture B4We: 16 equidistant steps W-C_e; W-M_e; W-Y_e; W-N; *rgb/cmy0*->*rgb_e* setrgbcolorTE961-3, Picture B5We: Sript and Landolt-rings N; C_e; M_e; Y_e; Z; PS operator: *rgb*->*rgb_e* setrgbcolorTE961-5, Picture B6We: Landolt-rings W-C_e; W-M_e; PS operator: *rgb*->*rgb_e* setrgbcolorTE961-7, Picture B7We: Landolt-rings W-Y_e; W-N; PS operator: *rgb*->*rgb_e* setrgbcolorinput: *rgb/cmyk* -> *rgb_e*
output: transfer to *cmy0_e*