






http://130.149.60.45/~farbmetrik/TN90/TN90L0NP.PDF /.PS; transfer output

N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: http://130.149.60.45/~farbmetrik/TN90/TN90L0NP.PDF /.PS;
technical information: http://www.ps.bam.de or http://130.149.60.45/~farbmetrik

TN900-3, Picture B1We: and 2 + 16 grey steps (nf); ; PS 3 colorimage

radial gratings W-C_e radial gratings W-M_e radial gratings W-Y_e radial gratings W-N radial gratings W-ZTN900-5, Picture B2We: radial gratings W-C_e; W-M_e; W-Y_e; W-N; PS operator: rgb->rgb_e setrgbcolorTN900-7, Picture B3We: 14 CIE-test colours and 2 + 16 grey steps (nf); PS operator:rgb/cmy0->rgb_e setrgbcolortest chart TN90; 2(ISO/IEC 15775 + ISO/IEC TR 24705)
chromatic test chart CMY, 3D=0, de=1, sRGBTN901-1, Picture B4We: 16 equidistant steps W-C_e; W-M_e; W-Y_e; W-N; rgb/cmy0->rgb_e setrgbcolorTN901-3, Picture B5We: Script Landolt-rings N; C_e; M_e; Y_e; Z; PS operator: rgb->rgb_e setrgbcolorTN901-5, Picture B6We: Landolt-rings W-C_e; W-M_e; PS operator:rgb->rgb_e setrgbcolorTN901-7, Picture B7We: Landolt-rings W-Y_e; W-N; PS operator:rgb->rgb_e setrgbcolorinput: rgb/cmyk -> rgb_e
output: transfer to rgb_e