




Farbmetrische Transformation $i=0$

$$x_i^* = x_0^* = w_0^* \text{ mit } x = o^*, l^*, v^*; w_0^* = 0,00$$





Farbmetrische Transformation $i=1$

$x_i^* = x_1^* = w_1^*$ mit $x = o^*, l^*, v^*$; $w_1^* = 0,06$




Farbmetrische Transformation $i=2$

$$x_i^* = x_2^* = w_2^* \text{ mit } x = o^*, l^*, v^*; w_2^* = 0,11$$




Farbmetrische Transformation $i=3$

$$x_i^* = x_3^* = w_3^* \text{ mit } x = o^*, l^*, v^*; w_3^* = 0,18$$




Farbmetrische Transformation $i=4$

$$x_i^* = x_4^* = w_4^* \text{ mit } x = o^*, l^*, v^*; w_4^* = 0,27$$





Farbmetrische Transformation $i=5$

$$x_i^* = x_5^* = w_5^* \text{ mit } x = o^*, l^*, v^*; w_5^* = 0,38$$



Farbmetrische Transformation $i=6$

$x_i^* = x_6^* = w_6^*$ mit $x = o^*, l^*, v^*$; $w_6^* = 0,52$



5 Stufen

Farbmetrische Transformation $i=7$

$$x_i^* = x_7^* = w_7^* \text{ mit } x = o^*, l^*, v^*; w_7^* = 0,70$$

