


$\log L/\Delta L$ luminance contrast
 sensitivity threshold • $L_g=0,1\text{cd/m}^2$
 $p_{CO}=0,3$

LI 0,4s A
equation




x y
A 0,39 0,41
 $A1=20.61$
 $A2=1.11$
 $A3=1.0$
 $A4=0.33$


$$F=A1(F3'/F3+F4'/F4);=I/\Delta L$$

$\log L/\Delta L$ luminance contrast sensitivity threshold • $L_g=1\text{cd/m}^2$
 $p_{C0}=0,3$

LI 0,4s A
equation




$\log L/\Delta L$ luminance contrast sensitivity threshold • $L_g=10\text{cd/m}^2$
 $p_{C0}=0,3$



$\log L/\Delta L$ luminance contrast sensitivity threshold • $L_g=100\text{cd/m}^2$
 $p_{CO}=0,3$

LI 0,4s A
equation



$\log L/\Delta L$ luminance contrast
 sensitivity threshold

$\bullet L_g = 1000 \text{ cd/m}^2$
 $p_{CO} = 0,3$

LI 0,4s A
equation

