





Picture C1: Radial gratings (Siemens-stars) N-W, W-N, N-Z and W-Z; Use of the PS operator *LAB* setcolor*




Picture C2: 5 visual equidistant L^* -gray steps + N_0 + W_1 ; Use of the PS operator *LAB* setcolor*




Picture C3: 16 visual equidistant L^* -gray steps; Use of the PS operator *LAB* setcolor*



Picture C4: Landolt-rings W-N; Use of the PS operator *LAB* setcolor*



Picture C5: Line raster under 45° (or 135°); Use of the PS operator *LAB* setcolor*



Picture C6: Line raster under 90° (or 0°); Use of the PS operator *LAB* setcolor*