




Radial grating (Siemens-star) $N-W$




Radial grating (Siemens-star) W-N




Radial grating (Siemens-star) N - Z





Radial grating (Siemens-star) W-Z




Picture C2: 5 visual equidistant L^* -grey steps + $N0$ + $W1$; Use of the PS operator LAB^* *setcolor*



Picture C3: 16 visual equidistant L^* -grey steps; Use of the PS operator LAB^* *setcolor*

Picture C4: Landolt-rings W-N; Use of the PS operator *LAB* setcolor*

Picture C5: Line raster under 45° (or 135°); Use of the PS operator *LAB* setcolor*

Picture C6: Line raster under 90° (or 0°); Use of the PS operator *LAB* setcolor*