




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *cmy0* setcmkcolor* (only)



Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *cmy0* setcmkcolor* (only)




Picture D6: Landolt-rings W-O and W-L; Use of PS operator *cmy0* setcmkcolor* (only)




Picture D7: Landolt-rings W-V and W-N; Use of PS operator *cmy0* setcmkcolor* (only)


Fig. D4 to D7 of ISO/IEC-test chart 4;




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator *olv* setrgbcolor* (only)



Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator *olv* setrgbcolor* (only)



Picture D6: Landolt-rings W-O and W-L; Use of PS operator *olv* setrgbcolor* (only)



Picture D7: Landolt-rings W-V and W-N; Use of PS operator *olv* setrgbcolor* (only)

ISO/IEC 15775 and input: mixture (m) of PS operators
DIS ISO/IEC 19839-X; output: *cmy0* / 000n* setcmkcolor*