




Picture C1: Radial gratings (Siemens-stars) N-W, W-N, N-Z and W-Z; PS operator: $w^*lin\ 1.0\ exp\ setgray$



Picture C2: 5 visual equidistant L^* -grey steps + N_0 + W_1 ; PS operator: $w^*lin\ 1.0\ exp\ setgray$



Picture C3: 16 visual equidistant L^* -grey steps; PS operator: $w^*lin\ 1.0\ exp\ setgray$

ISO/IEC-test chart no. 3 according to


ISO/IEC 15775 and DIS ISO/IEC 19839-X; input: $w^*lin\ 1.0\ exp\ setgray$
output: $w^*lin\ 1.0\ exp\ setgray$



Picture C4: Landolt-rings W-N; PS operator: $w^*lin\ 1.0\ exp\ setgray$



Picture C5: Line raster under 45° (or 135°); PS operator: $w^*lin\ 1.0\ exp\ setgray$



Picture C6: Line raster under 90° (or 0°); PS operator: $w^*lin\ 1.0\ exp\ setgray$