




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator cmy0* setcmkcolor (only)



Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator cmy0* setcmkcolor (only)




Picture D6: Landolt-rings W-O and W-L; Use of PS operator cmy0* setcmkcolor (only)




Picture D7: Landolt-rings W-V and W-N; Use of PS operator cmy0* setcmkcolor (only)


Fig. D4 to D7 of ISO/IEC-test chart 4;




Picture D4: 16 equidistant steps W-O, W-L, W-V and W-N; Use of PS operator olv* setrgbcolor (only)



Picture D5: Script and Landolt-rings N, O, L and V; Use of PS operator olv* setrgbcolor (only)



Picture D6: Landolt-rings W-O and W-L; Use of PS operator olv* setrgbcolor (only)



Picture D7: Landolt-rings W-V and W-N; Use of PS operator olv* setrgbcolor (only)

ISO/IEC 15775 and
DIS ISO/IEC 19839-X; input: mixture (m) of PS operators
output: cmy0* / 000n* setcmkcolor