

used coordinate
squares

LAB^{*}_{ORS18}

C
LAB^{*}_{ORS18}

LAB^{*}_{ORS18}

M
LAB^{*}_{ORS18}

LAB^{*}_{ORS18}

Y
LAB^{*}_{ORS18}

LAB^{*}_{ORS18}

O
LAB^{*}_{ORS18}

LAB^{*}_{ORS18}

L
LAB^{*}_{ORS18}


LAB^{*}_{ORS18}

V
LAB^{*}_{ORS18}

LAB^{*}_{ORS18}

N/W
LAB^{*}_{ORS18}

LAB^{*}_{ORS18}



16 equidistant CIELAB steps: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W, W-N and 14 CIE-test colours (left)

Test chart LE02: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White

input(ORS18): *LAB*^{*} *setcolor*
output(ORS18): *cmy0** / *000n** *setcmykcolor*