


See for similar files: <http://www.ps.bam.de/LE14/LE14.HTM>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=0,0?



used coordinate
surround center
*c000** *o11**
C
*1my0** *0lv**
*0m00** *1l1**
M
*c1y0** *o0v**
*00y0** *11v**
Y
*cm10** *o10**
*0my0** *1lv**
O
*c110** *o00**
*c0y0** *o1v**
L
*1m10** *0l0**
*cm00** *o11**
V
*11y0** *00v**
*cmv0** *olv**
N/W
*000k** *w**

BAM registration: 20030101-LE14/10S/S14E00SP.PS/.PDF
application for measurement of monitor (Yr=2.5) and printer output
BAM material: code=rha4ta

16 equidistant CIELAB steps: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W, W-N and 14 CIE-test colours (left)

Test chart LE14: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White

input ,ORS18: LAB* setcolor (2x)
output ,ORS18: Startup (S) data dependend