

See for similar files: <http://www.ps.bam.de/LE18/10L/L18E07FP.PS/.PDF>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=0,7; iTLS; oTLS, CIELAB

used coordinate
surround center

LAB^*_{TLS00} $c000^*$

C

LAB^*_{TLS00} $1my0^*$

LAB^*_{TLS00} $0m00^*$

M

LAB^*_{TLS00} $c1y0^*$

LAB^*_{TLS00} $00y0^*$

Y

LAB^*_{TLS00} $cm10^*$

LAB^*_{TLS00} $0my0^*$

O

LAB^*_{TLS00} $c110^*$

LAB^*_{TLS00} $c0y0^*$

L

LAB^*_{TLS00} $1m10^*$

LAB^*_{TLS00} $cm00^*$

V

LAB^*_{TLS00} $11y0^*$

LAB^*_{TLS00} $cmy0^*$

N/W

LAB^*_{TLS00} $000k^*$

BAM registration: 20030101-LE18/10L/L18E07FP.PS/.PDF
application for measurement of monitor (Yr=2.5) and printer output

BAM material: code=rha4ta

16 equidistant CIELAB steps: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W, W-N and 14 CIE-test colours (left)

Test chart LE18: 16 CIELAB steps of ISO/IEC 15775 input ,TLS00,ORS18: LAB^* setcolor (2x)
Chromatic-White, Chromatic-Black, Black-White output ,TLS00: w^* setgray