



See for similar files: <http://www.ps.bam.de/LE21/LE21.HTM>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=1,0?

BAM registration: 20030101-LE21/10S/S21E04SP.PS/.PDF BAM material: code=rha4ta
application for measurement of monitor (Yr=2.5) and printer output




16 equidistant CIELAB steps: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W (olv*), W-N (w*) and 14 CIE-test colours (left)


Test chart LE21: 16 CIELAB steps of ISO/IEC 15775 input(ORS18): olv* setrgbcolor
Chromatic-White, Chromatic-Black, Black-White output(ORS18): Startup (S) data dependend




Picture B4w: 16 equidistant steps W-C, W-M, W-Y and W-N; PS operator *olv* setrgbcolor* (only)



Picture B5w: Script and Landolt-rings N, M, C and Y; PS operator *olv* setrgbcolor* (only)




Picture B6w: Landolt-rings W-C and W-M; PS operator *olv* setrgbcolor* (only)




Picture B7w: Landolt-rings W-Y and W-N; PS operator *olv* setrgbcolor* (only)


Test chart LE21: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White




Picture D4w: 16 equidistant steps W-O, W-L, W-V and W-N; PS operator *olv* setrgbcolor / w* setgray*



Picture D5w: Script and Landolt-rings N, O, L and V; PS operator *olv* setrgbcolor / w* setgray*




Picture D6w: Landolt-rings W-O and W-L; PS operator *olv* setrgbcolor / w* setgray*




Picture D7w: Landolt-rings W-V and W-N; PS operator *olv* setrgbcolor / w* setgray*

input(ORS18): *olv* setrgbcolor*
output(ORS18): *Startup (S) data dependend*




See for similar files: <http://www.ps.barn.de/LE21/LE21.HTM>
Information and Order: <http://www.ps.barn.de> Version 2.0, io=1,0?




Picture B4n: 16 equidistant steps $N-C$, $N-M$, $N-Y$ and $N-W$; PS operator $olv^* setrgbcolor / w^* setgray$



Picture B5n: Script and Landolt-rings *W*, *M*, *C* and *Y*; PS operator *olv* setrgbcolor / w* setgray*




Picture B6n: Landolt-rings *N-C* and *N-M*; Use of PS operator *olv* setrgbcolor / w* setgray*




Picture B7n: Landolt-rings *N-Y* and *N-W*; PS operator *cmv0*/000n* setcmvcolor*




Test chart LE21: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White




Picture D4n: 16 equidistant steps *N-O*, *N-L*, *N-V* and *N-W*; PS operator *olv* setrgbcolor* (only)



Picture D5n: Script and Landolt-rings W , O , L and V ; PS operator `olv* setrgbcolor` (only)



Picture D6n: Landolt-rings *N-U* and *N-L*; Use of PS operator *olv** *setrgbcolor* (only)




Picture D7n: Landolt-rings *N-V* and *N-W*; PS operator *olv* setrgbcolor* (only)


input(ORS18): *olv* setrgbcolor*
 output(ORS18): *Startup (S) data depend*




BAM registration: 20030101-LE21/10S/S21E24SP.PS/.PDF BAM
 application for measurement of monitor (Yr=2.5) and printer output
 T A W

BAM material: code=rh4ta
put







Picture B4n: 16 equidistant steps $N-C$, $N-M$, $N-Y$ and $N-W$; PS operator $olv^* setrgbcolor / w^* setgray$




Picture B5n: Script and Landolt-rings W , M , C and Y ; PS operator $olv^* setrgbcolor / w^* setgray$




Picture B6n: Landolt-rings $N-C$ and $N-M$; Use of PS operator $olv^* setrgbcolor / w^* setgray$




Picture B7n: Landolt-rings $N-Y$ and $N-W$; PS operator $olv^* setrgbcolor / w^* setgray$




Test chart LE21: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White




Picture B4w: 16 equidistant steps $W-C$, $W-M$, $W-Y$ and $W-N$; PS operator $olv^* setrgbcolor$ (only)



Picture B5w: Script and Landolt-rings N , M , C and Y ; PS operator $olv^* setrgbcolor$ (only)




Picture B6w: Landolt-rings $W-C$ and $W-M$; PS operator $olv^* setrgbcolor$ (only)




Picture B7w: Landolt-rings $W-Y$ and $W-N$; PS operator $olv^* setrgbcolor$ (only)


input(ORS18): $olv^* setrgbcolor$
output(ORS18): *Startup (S) data dependend*




Picture D4n: 16 equidistant steps *N-O*, *N-L*, *N-V* and *N-W*; PS operator *olv* setrgbcolor* (only)




Picture D5n: Script and Landolt-rings *W*, *O*, *L* and *V*; PS operator *olv* setrgbcolor* (only)




Picture D6n: Landolt-rings *N-O* and *N-L*; Use of PS operator *olv* setrgbcolor* (only)




Picture D7n: Landolt-rings *N-V* and *N-W*; PS operator *olv* setrgbcolor* (only)




Test chart LE21: 16 CIELAB steps of ISO/IEC 15775
Chromatic-White, Chromatic-Black, Black-White




Picture D4w: 16 equidistant steps *W-O*, *W-L*, *W-V* and *W-N*; PS operator *olv* setrgbcolor / w* setgray*



Picture D5w: Script and Landolt-rings *N*, *O*, *L* and *V*; PS operator *olv* setrgbcolor / w* setgray*



Picture D6w: Landolt-rings *W-O* and *W-L*; PS operator *olv* setrgbcolor / w* setgray*



Picture D7w: Landolt-rings *W-V* and *W-N*; PS operator *olv* setrgbcolor / w* setgray*

input(ORS18): *olv* setrgbcolor*
output(ORS18): *Startup (S) data dependend*

