

See for similar files: <http://www.ps.bam.de/LE32/10Q/Q32E04FP.PS/.PDF>  
Information and Order: <http://www.ps.bam.de> Version 2.0, io=5,4; iTLS; oTLS, CIELAB

used coordinate squares

*LAB*<sup>\*</sup><sub>TLS00</sub>

**C**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>

**M**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>

**Y**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>

**O**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>

**L**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>

**V**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>


**N/W**  
*LAB*<sup>\*</sup><sub>TLS00</sub>

*LAB*<sup>\*</sup><sub>TLS00</sub>


16 equidistant CIELAB steps: C-W, C-N, M-W, M-N, Y-W, Y-N, O-W, O-N, L-W, L-N, V-W, V-N, N-W, W-N and 14 CIE-test colours (left)

Test chart LE32: 16 CIELAB steps of ISO/IEC 15775  
Chromatic-White, Chromatic-Black, Black-White


input(TLS00): *LAB*<sup>\*</sup> setcolor  
output(TLS00): *lab*<sup>\*</sup> setcolor




Picture D4w: 16 equidistant steps W-C, W-M, W-Y and W-N; PS operator LAB\* setcolor




Picture B5w: Script and Landolt-rings N, C, M and Y; PS operator LAB\* setcolor




Picture B6w: Landolt-rings W-C and W-M; PS operator LAB\* setcolor




Picture B7w: Landolt-rings W-Y and W-N; PS operator LAB\* setcolor




Picture D4w: 16 equidistant steps W-O, W-L, W-V and W-N; PS operator LAB\* setcolor



Picture D5w: Script and Landolt-rings N, O, L and V; PS operator LAB\* setcolor




Picture D6w: Landolt-rings W-O and W-L; PS operator LAB\* setcolor



Picture D7w: Landolt-rings W-V and W-N; PS operator LAB\* setcolor


www.ps.bam.de/LE32/10Q/Q32E24FP.PS/.PDF; linearized output  
F: Output Linearization (OL) data LE32/10Q/Q32E24FP.DAT in File (F)




Picture B4n: 16 equidistant steps *W-C*, *W-M*, *W-Y* and *W-N*; PS operator *LAB\* setcolor*




Picture D5n: Script and Landolt-rings *W*, *C*, *M* and *Y*; PS operator *LAB\* setcolor*




Picture B6n: Landolt-rings *N-C* and *N-M*; PS operator *LAB\* setcolor*




Picture B7n: Landolt-rings *W-Y* and *W-N*; PS operator *LAB\* setcolor*




Test chart LE32: 16 CIELAB steps of ISO/IEC 15775  
Chromatic-White, Chromatic-Black, Black-White




Picture D4n: 16 equidistant steps *W-O*, *W-L*, *W-V* and *W-N*; PS operator *LAB\* setcolor*



Picture D5n: Script and Landolt-rings *W*, *O*, *L* and *V*; PS operator *LAB\* setcolor*



Picture D6n: Landolt-rings *N-O* and *N-L*; PS operator *LAB\* setcolor*




Picture D7n: Landolt-rings *N-V* and *N-N*; PS operator *LAB\* setcolor*

input(TLS00): *LAB\* setcolor*  
output(TLS00): *lab\* setcolor*




Test chart LE32: 16 CIELAB steps of ISO/IEC 15775  
Chromatic-White, Chromatic-Black, Black-White




Picture B4n: 16 equidistant steps W-C, W-M, W-Y and W-N; PS operator LAB\* setcolor





Picture D5n: Script and Landolt-rings W, C, M and Y; PS operator LAB\* setcolor




Picture B6n: Landolt-rings N-C and N-M; PS operator LAB\* setcolor




Picture B7n: Landolt-rings W-Y and W-N; PS operator LAB\* setcolor




Picture D4w: 16 equidistant steps W-C, W-M, W-Y and W-N; PS operator LAB\* setcolor




Picture B5w: Script and Landolt-rings N, C, M and Y; PS operator LAB\* setcolor




Picture B6w: Landolt-rings W-C and W-M; PS operator LAB\* setcolor




Picture B7w: Landolt-rings W-Y and W-N; PS operator LAB\* setcolor







Picture D4n: 16 equidistant steps W-O, W-L, W-V and W-N; PS operator LAB\* setcolor





Picture D5n: Script and Landolt-rings W, O, L and V; PS operator LAB\* setcolor




Picture D6n: Landolt-rings N-O and N-L; PS operator LAB\* setcolor




Picture D7n: Landolt-rings N-V and N-N; PS operator LAB\* setcolor




Picture D4w: 16 equidistant steps W-O, W-L, W-V and W-N; PS operator LAB\* setcolor



Picture D5w: Script and Landolt-rings N, O, L and V; PS operator LAB\* setcolor



Picture D6w: Landolt-rings W-O and W-L; PS operator LAB\* setcolor



Picture D7w: Landolt-rings W-V and W-N; PS operator LAB\* setcolor

