



See for similar files: <http://www.ps.bam.de/LE64/10Q/Q64E02NP.PS/.PDF>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=0&1,0&1

BAM registration: 20030101-LE64/10Q/Q64E02NP.PS/.PDF BAM material: code=rha4ta
application for measurement of monitor (Yr=2.5) and printer output

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	used coordinate	surround center
01																		<i>V</i>	$1m00^*$ $0l1^*$
02																		<i>M</i>	$c100^*$ $o01^*$
03																		<i>O</i>	$01y0^*$ $10v^*$
04																		<i>Y</i>	$0m10^*$ $1l0^*$
05																		<i>L</i>	$c010^*$ $o10^*$
06																		<i>C</i>	$10y0^*$ $01v^*$
07																		<i>Mw</i>	$xm00^*$ $xl1^*$
08																		<i>Yw</i>	$cx00^*$ $ox1^*$
09																		<i>Cw</i>	$0xy0^*$ $1xv^*$
10																		<i>Mn</i>	$1mx0^*$ $xl0^*$
11																		<i>Yn</i>	$c1x0^*$ $ox0^*$
12																		<i>Cn</i>	$x1y0^*$ $0xv^*$
13																		<i>W</i>	$cmy0^*$ olv^*
14																		<i>N</i>	$000n^*$ w^*

