

See for similar files: <http://www.ps.bam.de/LE65/10L/L65E00FP.PS/.PDF>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=0&5,0; iORS; oORS, CIELAB

BAM registration: 20030101-LE65/10L/L65E00FP.PS/.PDF
application for measurement of monitor (Yr=2.5) and printer output
BAM material: code=rha4ta

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	used coordinate	surround center
01																		<i>V</i>	<i>1m00*</i> <i>LAB*</i> _{ORS18}
02																		<i>M</i>	<i>c100*</i> <i>LAB*</i> _{ORS18}
03																		<i>O</i>	<i>01y0*</i> <i>LAB*</i> _{ORS18}
04																		<i>Y</i>	<i>0m10*</i> <i>LAB*</i> _{ORS18}
05																		<i>L</i>	<i>c010*</i> <i>LAB*</i> _{ORS18}
06																		<i>C</i>	<i>10y0*</i> <i>LAB*</i> _{ORS18}
07																		<i>Mw</i>	<i>xm00*</i> <i>LAB*</i> _{ORS18}
08																		<i>Yw</i>	<i>cx00*</i> <i>LAB*</i> _{ORS18}
09																		<i>Cw</i>	<i>0xy0*</i> <i>LAB*</i> _{ORS18}
10																		<i>Mn</i>	<i>1mx0*</i> <i>LAB*</i> _{ORS18}
11																		<i>Yn</i>	<i>c1x0*</i> <i>LAB*</i> _{ORS18}
12																		<i>Cn</i>	<i>x1y0*</i> <i>LAB*</i> _{ORS18}
13																		<i>W</i>	<i>cmy0*</i> <i>LAB*</i> _{ORS18}
14																		<i>N</i>	<i>000n*</i> <i>LAB*</i> _{ORS18}