



See for similar files: <http://www.ps.bam.de/LE69/10S/S69E01SP.PS/.PDF>
Information and Order: <http://www.ps.bam.de> Version 2.0, io=5&1,0?

BAM registration: 20030101-LE69/10S/S69E01SP.PS/.PDF
application for measurement of monitor (Yr=2.5) and printer output

BAM material: code=rha4ta

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q		used coordinate surround center
01																		<i>V</i>	$LAB^*_{ORS18} 0/1^*$
02																		<i>M</i>	$LAB^*_{ORS18} 001^*$
03																		<i>O</i>	$LAB^*_{ORS18} 10v^*$
04																		<i>Y</i>	$LAB^*_{ORS18} 110^*$
05																		<i>L</i>	$LAB^*_{ORS18} 010^*$
06																		<i>C</i>	$LAB^*_{ORS18} 01v^*$
07																		<i>Mw</i>	$LAB^*_{ORS18} x/1^*$
08																		<i>Yw</i>	$LAB^*_{ORS18} 0x1^*$
09																		<i>Cw</i>	$LAB^*_{ORS18} 1xv^*$
10																		<i>Mn</i>	$LAB^*_{ORS18} x/0^*$
11																		<i>Yn</i>	$LAB^*_{ORS18} 0x0^*$
12																		<i>Cn</i>	$LAB^*_{ORS18} 0xv^*$
13																		<i>W</i>	$LAB^*_{ORS18} 0lv^*$
14																		<i>N</i>	$LAB^*_{ORS18} w^*$

