


<http://130.149.60.45/~farbmetrik/PE46/PE46L0NP.PDF> / .PS; transfer output
N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 2/2

see similar files: <http://130.149.60.45/~farbmetrik/PE46/PE46L0NP.PDF> / .PS
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetrik>



TUB-test chart PE46; standard test chart
1080 standard colours, 3D=0, de=0, cmy0

input: *rgb/cmyk* -> *rgb_d*
output: transfer to *cmy0_d*

TUB registration: 20130201-PE46/PE46L0NP.PDF / .PS
application for measurement of offset print output, separation cmy0 (CMY0)

TUB material: code=rha4ta