


T^* Amount of
threshold steps

• $L_g = 0,1 \text{ cd/m}^2$


x y
 A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 1 \text{ cd/m}^2$


x y
A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 10 \text{ cd/m}^2$


x y
A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

● $L_g = 100 \text{ cd/m}^2$

x y
 A 0,39 0,41 LI 0,4s A
equation



T^* Amount of
threshold steps

• $L_g = 1000 \text{ cd/m}^2$

x y
A 0,39 0,41 LI 0,4s A
equation

