


<http://130.149.60.45/~farbmetrik/TN96/TN96L0NP.PDF> /.PS; overføring output

N: ingen 3D-linearisering (OL) i fil (F) eller PS-startup (S), side 2/2



TN960-3, Picture B1Wd: and 2 + 16 grey steps (nf); ; PS 4 colorimage



radial gratings W-C_d radial gratings W-M_d radial gratings W-Y_d radial gratings W-N radial gratings W-Z


TN960-5, Picture B2Wd: radial gratings W-C_d; W-M_d; W-Y_d; W-N; PS operator: *rgb*→*rgb_d* setrgbcolor




TN960-7, Picture B3Wd: 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator: *rgb/cmy0*→*rgb_d* setrgbcolor




prøveplansje TN96; 2(ISO/IEC 15775 + ISO/IEC TR 24705)input: *rgb/cmyk* → *rgb_d*
kromatisk prøveplansje CMY, 3D=0, de=0, *cmy0*
output: overføring til *cmy0_d*




TN961-1, Picture B4Wd: 16 equidistant steps W-C_d; W-M_d; W-Y_d; W-N; *rgb/cmy0*→*rgb_d* setrgbcolor



TN961-3, Picture B5Wd: Script Landolt-rings N; C_d; M_d; Y_d; Z; PS operator: *rgb*→*rgb_d* setrgbcolor



TN961-5, Picture B6Wd: Landolt-rings W-C_d; W-M_d; PS operator: *rgb*→*rgb_d* setrgbcolor



TN961-7, Picture B7Wd: Landolt-rings W-Y_d; W-N; PS operator: *rgb*→*rgb_d* setrgbcolor



TUB registrering: 20150701-TN96/TN96L0NP.PDF /.PS
anvendelse for måling av ofsettrykk output, separasjoncmy0 (CMY0)

TUB-material: code=rh44a

se lignende filer: <http://130.149.60.45/~farbmetrik/TN96/TN96L0NP.PDF> /.PS
teknisk informasjon: <http://www.ps.bam.de> eller <http://130.149.60.45/~farbmetrik>