


http://130.149.60.45/~farbmetrik/TN99/TN99L0NA.TXT /PS; start output
N: ingen 3D-linearisering (OL) i fil (F) eller PS-startup (S), side 1/22




TN990-3, Picture D1W-: and 2 + 16 grey steps (sf); ; PS operator: 4 colorimage



radial gratings W-C- radial gratings W-M- radial gratings W-Y- radial gratings W-N radial gratings W-Z


TN990-5, Picture B2W-: radial gratings W-C-; W-M-; W-Y-; W-N; PS operator: rgb setrgbcolor




TN990-7, Picture B3W-: 14 CIE-test colours and 2 + 16 grey steps (sf); PS operator:rgb/cmy0 set(rgb/cmyk)color




prøveplansje TN99; 2(ISO/IEC 15775 + ISO/IEC TR 24705)input: rgb/cmyk -> w/rgb/cmyk-
kromatisk prøveplansje CMY
output: ingen ending




TN991-1, Picture B4W-: 16 equidistant steps W-C-; W-M-; W-Y-; W-N; rgb/cmy0 set(rgb/cmyk)color



TN991-3, Picture B5W-: Script Landolt-rings N; C-; M-; Y-; Z; PS operator: rgb->rgb_ setrgbcolor



TN991-5, Picture B6W-: Landolt-rings W-C-; W-M-; PS operator:rgb setrgbcolor



TN991-7, Picture B7W-: Landolt-rings W-Y-; W-N; PS operator:rgb setrgbcolor

TN99sop

TUB registrering: 20150701-TN99/TN99L0NA.TXT /PS
anvendelse for måling av laserprinter output

TUB-material: code=rh4ta