



$L/\Delta L$ luminance contrast sensitivity threshold

• $L_g=0,1\text{cd/m}^2$




$L/\Delta L$ luminance contrast sensitivity threshold

• $L_g = 1 \text{ cd/m}^2$




$L/\Delta L$ luminance contrast sensitivity threshold

• $L_g = 10 \text{ cd/m}^2$



$L/\Delta L$ luminance contrast
sensitivity threshold

• $L_g = 100 \text{ cd/m}^2$



$L/\Delta L$ luminance contrast
sensitivity threshold

• $L_g = 1000 \text{ cd/m}^2$

$x \quad y$
A 0,39 0,41 **LI** 0,4s **A**
A1=172.8 **equation**
A2=-2.61
A3=1.0
A4=0.33

$$F = A1(F3'/F3 + F4'/F4), = L / \Delta L$$

