

















<http://130.149.60.45/~farbmetriK/WE16/WE16L0N1.TXT/.PS>; start output

N: no 3D-linearization (OL) in file (F) or PS-startup (S), page 1/1

see similar files: <http://130.149.60.45/~farbmetriK/WE16/WE16.htm>
technical information: <http://www.ps.bam.de> or <http://130.149.60.45/~farbmetriK>



TUB-test chart WE16; CIELAB and LABJND formulae
Threshold lightness, difference, contrast, and sensitivity

input: w/rgb/cmyk → w/rgb/cmyk...