



Colour management for output linearization of a 9 step grey scale



Colour management for output linearization of a 9 step grey scale




gen40-3n

gen41-3n



gen40-5n, Test samples: 3, 5 and 9 colour steps, greu=0,500, expu=1,000, expa=1,000



gen40-7n, Test samples: 3, 5 and 9 colour steps, greu=0,500, expu=2,000, expa=2,000