

# Colour management for output linearization of a 9 step grey scale

*\*(star-dash) coordinates  
 of real output with real  
 display reflection in office room;  
 lighter (positiv P) real output*  
 $w^{*'} \text{ output} = f_r [w^{*} \text{ input}]$   
 $w^{*'} \text{ output} = [w^{*} \text{ input}]^{1,000}$   
 $= w^{*'} \text{ output}$

