

Colour management for output linearization of a 9 step grey scale

**(star-dash) coordinates
 of real output with real
 display reflection in office room;
 lighter (positiv P) real output*
 $w^{*'} \text{ output} = f_r [w^{*} \text{ input}]$
 $w^{*'} \text{ output} = [w^{*} \text{ input}]^{1,000}$
 $= w^{*'} \text{ output}$

